


CLS : CLOSE LIMIT SWITCH (250VCA 16A)
 OLS : OPEN LIMIT SWITCH (250VCA 16A)
 CTS : CLOSE TORQUE SWITCH (250VCA 16A)
 OTS : OPEN TORQUE SWITCH (250VCA 16A)
 TP : THERMAL PROTECTOR (250VCA 15A)

*EACH ACTUATOR SHOULD BE POWERED THROUGH ITS OWN INDIVIDUAL SWITCH OR RELAY CONTACTS TO PREVENT CROSS FEED BETWEEN TWO OR MORE ACTUATORS

	CLOSE	OPEN
CLS 1-2		
CLS 1-3		
OLS 1-2		
OLS 1-3		
ACLS 1-2		
ACLS 1-3		
AOLS 1-2		
AOLS 1-3		



NA050	1	NA250	1	△					
NA038	1	NA200	1	SYM	E C N NO	CHANGES	DATE	SIGN	APPD
NA028	1	NA150	1	DRAW	H,J KWON	PART NAME AC 1PH WIRING DIAGRAM			
NA019	1	NA100	1	CHECK					
NA015	1	NA080	1	APPD		DWG NO. NS-11000-C			
APPLICATION	NA060	1	DATE	'18,07,27					