


CLS : CLOSE LIMIT SWITCH (250VAC 16A)
 OLS : OPEN LIMIT SWITCH (250VAC 16A)
 CTS : CLOSE TORQUE SWITCH (250VAC 16A)
 OTS : OPEN TORQUE SWITCH (250VAC 16A)

CLOSE		OPEN
CLS 1-2		
CLS 1-3		
OLS 1-2		
OLS 1-3		
CTS 1-3	* CLOSING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING CLOSING CYCLE	
OTS 1-3	* OPENING TORQUE SWITCH INTERRUPTS CONTROL IF MACHANICAL OVERLOAD OCCURS DURING OPENING CYCLE	



			△					
			SYM	E C N NO	CHANGES	DATE	SIGN	APPD
			DRAW	H.J. KIM	PART NAME	1PH WIRING DIAGRAM SUPERCAP, ALS, PCU		
AO19	1		CHECK	K.H. OH				
AO15	1		APPD		DWG NO.	NS-1256S-A		
APPLICATION			DATE	'20.04.20				