


CLS : CLOSE LIMIT SWITCH (250VAC 16A)
OLS : OPEN LIMIT SWITCH (250VAC 16A)
CTS : CLOSE TORQUE SWITCH (250VAC 16A)
OTS : OPEN TORQUE SWITCH (250VAC 16A)
ACLS : AUX,CLOSE LIMIT SWITCH (250VAC 16A)
AOLS : AUX,OPEN LIMIT SWITCH (250VAC 16A)

	CLOSE	OPEN
CLS 1-2		
OLS 1-2		
ACLS 1-3		
AOLS 1-3		
CTS 1-3	* CLOSING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING CLOSING CYCLE	
OTS 1-3	* OPENING TORQUE SWITCH INTERRUPTS CONTROL IF MACHANICAL OVERLOAD OCCURS DURING OPENING CYCLE	

AC 1PH (V)

PROPOSE CUSTOMER'S WIRING
ACTUATOR WIRING



NA50	1		1	DRAW K.H. OH	△					
NA38	1		1		SYM	E C N NO	CHANGES	DATE	SIGN	APPD
NA28	1	NA100	1		CHECK	PART NAME 1PH WIRING DIAGRAM SPEED CONTRL, ALS				
NA19	1	NA80	1		APPD					
NA15	1	NA60	1							
APPLICATION				DATE 21.11.11.	DWG NO.	NS-B1200-B				