




		DRAW	K.H. OH	△						
		CHECK	K.H. OH	SYM	E C N NO		CHANGES		DATE	SIGN
A009 1		APPD M.Y. HWANG		PART NAME		1PH WIRING DIAGRAM		DATE		APPD
A006 1		DATE 22.10.11.		DWG NO.		INTEGRAL ON/OFF				
APPLICATION						NU-201-B				