


		CLOSE	OPEN
CLS 1-2			
CLS 1-3			
OLS 1-2			
OLS 1-3			
ACLS 1-2			
ACLS 1-3			
AOLS 1-2			
AOLS 1-3			



		△					
		SYM	E C N NO	CHANGES	DATE	SIGN	APPD
SR30	1	DRAW	H.J KWON	PART NAME	1PH WIRING DIAGRAM ALS,LCU FAIL CLOSE		
SR10	1	CHECK					
SR05	1	APPD					
APPLICATION		DATE	'13,01,23	DWG NO.	RUC-1270-C		