


CLS : CLOSE LIMIT SWITCH (250VAC 15A)
OLS : OPEN LIMIT SWITCH (250VAC 15A)
CTS : CLOSE TORQUE SWITCH (250VAC 15A)
OTS : OPEN TORQUE SWITCH (250VAC 15A)
ACLS : AUX. CLOSE LIMIT SWITCH (250VAC 15A)
AOLS : AUX.OPEN LIMIT SWITCH (250VAC 15A)
TP : THERMAL PROTECTOR (250VAC 15A)
CC : CLOSE MAGNETIC COIL
OC : OPEN MAGNETIC COIL

CLOSE		OPEN	
CLS 1-2			
CLS 1-3			
OLS 1-2			
OLS 1-3			
ACLS 1-2			
ACLS 1-3			
AOLS 1-2			
AOLS 1-3			



				△					
SR30	1			SYM	E C N NO	CHANGES	DATE	SIGN	APPD
SR20	1			DRAW	H,J KWON	PART NAME	3PH WIRING DIAGRAM FAIL OPEN, ALS, LCU		
SR10	1			CHECK					
SR05	1			APPD					
APPLICATION				DATE	' 14,06,11	DWG NO.	RUO-3270-D		