


	CLOSE	OPEN
CLS 1-2		
CLS 1-3		
OLS 1-2		
OLS 1-3		
CTS 1-3	* CLOSING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING CLOSING CYCLE	
OTS 1-3	* OPENING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING OPENING CYCLE	



				△					
				SYM	E C N NO	CHANGES	DATE	SIGN	APPD
				DRAW	H.J. KIM	PART NAME	1PH WIRING DIAGRAM SUPER CAP		
NL10	1			CHECK	K.H. OH				
NLO8	1			APPD					
APPLICATION				DATE	20.02.05.	DWG NO.	LS-16S00-A		