


CLS : CLOSE LIMIT SWITCH (250VAC 16A)
OLS : OPEN LIMIT SWITCH (250VAC 16A)
CTS : CLOSE TORQUE SWITCH (250VAC 16A)
OTS : OPEN TORQUE SWITCH (250VAC 16A)

CLOSE		OPEN	
CLS 1-2			
OLS 1-2			
ACLS 1-3			
AOLS 1-3			
* CLOSING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING CLOSING CYCLE			
* OPENING TORQUE SWITCH INTERRUPTS CONTROL IF MACHANICAL OVERLOAD OCCURS DURING OPENING CYCLE			



APPLICATION	DRAW	H.S PARK	△					
	CHECK		SYM	E C N NO	CHANGES	DATE	SIGN	APPD
	APPD		PART NAME 1PH WIRING DIAGRAM SPEED CONTROL, ALS, PCU					
	DATE	22.10.26	DWG NO.	LS-B1250-B				