


CLS : CLOSE LIMIT SWITCH (250VAC 16A)
 OLS : OPEN LIMIT SWITCH (250VAC 16A)
 CTS : CLOSE TORQUE SWITCH (250VAC 16A)
 OTS : OPEN TORQUE SWITCH (250VAC 16A)

CLOSE		OPEN
CLS 1-2		
CLS 1-3		
OLS 1-2		
OLS 1-3		
CTS 1-3	* CLOSING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING CLOSING CYCLE	
OTS 1-3	* OPENING TORQUE SWITCH INTERRUPTS CONTROL IF MACHANICAL OVERLOAD OCCURS DURING OPENING CYCLE	



				△					
				SYM	E C N NO	CHANGES	DATE	SIGN	APPD
				DRAW	H.J. KIM	PART NAME 1PH WIRING DIAGRAM SUPER CAP,ALS			
				CHECK	K.H. OH				
A028	1			APPD		DWG NO. NE-126SO-A			
APPLICATION				DATE	20.05.28.				