


CLS : CLOSE LIMIT SWITCH (250VAC 6A)
OLS : OPEN LIMIT SWITCH (250VAC 6A)
CTS : CLOSE TORQUE SWITCH (250VAC 6A)
OTS : OPEN TORQUE SWITCH (250VAC 6A)
TP : THERMAL PROTECTOR (250VAC 15A)

CLOSE		OPEN
CLS 1-2		
CLS 1-3		
OLS 1-2		
OLS 1-3		
CTS 1-3		* CLOSING TORQUE SWITCH INTERRUPTS CONTROL IF MECHANICAL OVERLOAD OCCURS DURING CLOSING CYCLE
OTS 1-3		* OPENING TORQUE SWITCH INTERRUPTS CONTROL IF MACHANICAL OVERLOAD OCCURS DURING OPENING CYCLE



A050	1	A250	1	△					
A038	1	A200	1	SYM	E C N NO	CHANGES	DATE	SIGN	APPD
A028	1	A150	1	DRAW	H,J KWON	PART NAME 1PH WIRING DIAGRAM PCU,LCU(M)			
A019	1	A100	1	CHECK					
A015	1	A080	1	APPD					
APPLICATION	A060	1	DATE	'13,07,25	DWG NO.	NS-15700-E			